

Outline and installation drawing of Log M

This surface should leave a minimum clearance of 70mm for tools and wiring.

