

Outline and installation drawing of Mech-Eye Pro XS-V3

This surface should leave a minimum clearance of 70mm for tools and wiring.

